



## **FHC Track Repair Cap - 96" - Stainless Steel - Universal Fit - 5 Piece Pack**

**Item No.** D1579

### **Features, Advantages, and Benefits**

- Repairs existing damaged patio or closet door tracks
- Extruded Stainless Steel Construction
- 96 inches long
- Can be cut to length

- Fits most patio or closet door tracks
- Use with a thin bead of silicon glue to help keep it firmly in position

**Description:** OverviewD 1579 is a 96 inch stainless steel track cap used to repair damaged patio or wardrobe door tracks. It can be cut to size. After the old track is prepared by grinding any spots that are wider than the original track width and cleaning it, the new track is simply pressed onto the old track after squirting a thin bead of silicone glue in the replacement track. Using a rubber mallet and a block of wood, the replacement track is snapped down over the old track.